

## Temperature sensor type K (NiCrNi)

---

### PAN TAUCHFÜHLER ohne Adapter

Temperature point sensor, K thermocouple  $-50^{\circ}$  -  $+400^{\circ}\text{C}$  +  
adapter plug for connection to multimeter without adapter

Temperature immersion sensor  $-50^{\circ}$  -  $+600^{\circ}\text{C}$  K thermocouple, l =  
150 mm (without adapter)  
(not suitable for item PAN 185 ! )

